

## Instructions | Part#: BM4031

Case/IH, Blower Motor Update Kit

## Fits Case/IH Models:

Tractors 1896, 2090, 2094, 2096, 2290, 2294, 2390, 2394, 2470, 2590, 2594, 2670, 2870, 3294, 3394, 3594, 4490, 4494, 4690, 4694, 4890, 4894, 4994

Crawler 1150E, 1150G, 1150H, 1450B

Backhoe 580 Super E, 580D, 580G, 680H, 680K, 680L

Ford/New Holland 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A



When replacing original 2 wire blower assembly with new 4 wire, high efficiency assembly you must bypass original resistor and connect wires (red, yellow, orange) directly to blower switch. New 4 wire motors have new style resistor built in to motor. Leave the (C) constant power & the (B) Battery terminal hooked up in their original locations on switch.

